

# Specific Heat

## Measurement Data

### Heat capacity option using AC method

This method is particularly convenient for studies of phase transitions, as it allows to take data continuously as the sample is taken through a transition, either by ramping the temperature or the magnetic field. Record-high sensitivity allows measuring very small samples (down to microgram range).

